

# Condition Report

|                                        |           |             |                              |            |              |
|----------------------------------------|-----------|-------------|------------------------------|------------|--------------|
| Prepared On: 09/17/2026 11:45 AM       |           |             | Dealership: Drive a Dream    |            |              |
| Masked VIN: XXXXXXXXSU056144           |           |             | Year: 2025                   |            |              |
| Make: Lexus                            |           |             | Model: ES                    |            |              |
| Trim: ES 300h w/ Premium Package       |           |             | Odometer: 14671              |            |              |
| Engine: 2.5L I4 DOHC 16v VVT-Ie Engine |           |             | Transmission: Automatic      |            |              |
| Body: Sedan                            |           |             | Fuel: Hybrid-Electric        |            |              |
| Exterior Color: Matador Red Mica       |           |             | Interior Color: Acorn        |            |              |
| General Condition                      |           |             |                              |            |              |
| Odometer Status:                       |           |             | A/C Working:                 |            |              |
| Prior Paint: No                        |           |             | Engine Light On: No          |            |              |
| Total Panels Painted: 0                |           |             | ABS Light On: No             |            |              |
| Replaced Panels: No                    |           |             | Airbag Light On: No          |            |              |
| Total Panels Replaced: 0               |           |             | Airbag Deployed: No          |            |              |
| Structural Damage: No                  |           |             | History Check Problem: No    |            |              |
| Flood Damage: No                       |           |             | Odor: No                     |            |              |
| Fire Damage: No                        |           |             | Glass Damage: No             |            |              |
| Hail Damage: No                        |           |             | Mechanical Damage: No        |            |              |
| Number of Keys:                        |           |             | Title Country: United States |            |              |
| Number of Fobs:                        |           |             | Title State:                 |            |              |
| Keyless Entry: No                      |           |             | Title Status:                |            |              |
| Manuals: No                            |           |             | Title Type:                  |            |              |
| Police Use: No                         |           |             | Livery Use: No               |            |              |
| Taxi Use: No                           |           |             | Grey Market: No              |            |              |
| Canadian Vehicle: No                   |           |             | Sale Lights: No Light        |            |              |
| Wheels & Tires                         |           |             |                              |            |              |
| Location                               | Condition | Tread Depth | Manufacturer                 | Wheel Size | Wheel Damage |
| Right Front                            |           |             |                              |            |              |
| Left Front                             |           |             |                              |            |              |
| Right Rear                             |           |             |                              |            |              |
| Left Rear                              |           |             |                              |            |              |
| Right Rear Inner                       |           |             |                              |            |              |
| Left Rear Inner                        |           |             |                              |            |              |
| Spare                                  |           |             |                              |            |              |
| Damage                                 |           |             |                              |            |              |
| Prior Paint Location                   |           |             |                              |            |              |
| Prior Paint Condition                  |           |             |                              |            |              |
| Exterior Damage: No                    |           |             |                              |            |              |
| Interior Damage: No                    |           |             |                              |            |              |
| Mechanical Damage: No                  |           |             |                              |            |              |
| Notes                                  |           |             |                              |            | CR Score     |
|                                        |           |             |                              |            | -            |