

# Condition Report

|                                      |                                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
|--------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|--------------|------------|--------------|
| Prepared On: 09/03/2026 05:31 PM     | Dealership: Amazing Luxury Cars                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Masked VIN: XXXXXXXXXND004494        | Year: 2022                                                                                                                                                                                                                                                                                                                                    |             |              |            |              |
| Make: Audi                           | Model: SQ7                                                                                                                                                                                                                                                                                                                                    |             |              |            |              |
| Trim: Premium Plus                   | Odometer: 78584                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Engine: 4.0L TFSI 8-Cyl 500hp Engine | Transmission: Automatic                                                                                                                                                                                                                                                                                                                       |             |              |            |              |
| Body: SUV                            | Fuel: Gas                                                                                                                                                                                                                                                                                                                                     |             |              |            |              |
| Exterior Color:                      | Interior Color: Black                                                                                                                                                                                                                                                                                                                         |             |              |            |              |
| General Condition                    |                                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Odometer Status: No Issues           | A/C Working: Yes                                                                                                                                                                                                                                                                                                                              |             |              |            |              |
| Prior Paint: No                      | Engine Light On: No                                                                                                                                                                                                                                                                                                                           |             |              |            |              |
| Total Panels Painted: 0              | ABS Light On: No                                                                                                                                                                                                                                                                                                                              |             |              |            |              |
| Replaced Panels: No                  | Airbag Light On: No                                                                                                                                                                                                                                                                                                                           |             |              |            |              |
| Total Panels Replaced: 0             | Airbag Deployed: No                                                                                                                                                                                                                                                                                                                           |             |              |            |              |
| Structural Damage: No                | History Check Problem: No                                                                                                                                                                                                                                                                                                                     |             |              |            |              |
| Flood Damage: No                     | Odor: No                                                                                                                                                                                                                                                                                                                                      |             |              |            |              |
| Fire Damage: No                      | Glass Damage: No                                                                                                                                                                                                                                                                                                                              |             |              |            |              |
| Hail Damage: No                      | Mechanical Damage: No                                                                                                                                                                                                                                                                                                                         |             |              |            |              |
| Number of Keys: 1                    | Title Country: United States                                                                                                                                                                                                                                                                                                                  |             |              |            |              |
| Number of Fobs: 1                    | Title State:                                                                                                                                                                                                                                                                                                                                  |             |              |            |              |
| Keyless Entry: Yes                   | Title Status: Present                                                                                                                                                                                                                                                                                                                         |             |              |            |              |
| Manuals: No                          | Title Type: Clear                                                                                                                                                                                                                                                                                                                             |             |              |            |              |
| Police Use: No                       | Livery Use: No                                                                                                                                                                                                                                                                                                                                |             |              |            |              |
| Taxi Use: No                         | Grey Market: No                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Canadian Vehicle: No                 | Sale Lights: Green Light                                                                                                                                                                                                                                                                                                                      |             |              |            |              |
| Wheels & Tires                       |                                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Location                             | Condition                                                                                                                                                                                                                                                                                                                                     | Tread Depth | Manufacturer | Wheel Size | Wheel Damage |
| Right Front                          |                                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Left Front                           |                                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Right Rear                           |                                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Left Rear                            |                                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Right Rear Inner                     |                                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Left Rear Inner                      |                                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Spare                                |                                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Damage                               |                                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Prior Paint Location                 |                                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Prior Paint Condition                |                                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Exterior Damage: Yes                 | <ul style="list-style-type: none"><li>Panel: front_bumper, Condition: chipped_multiple, Size: one_to_two</li><li>Panel: front_bumper, Condition: heavy_scratch, Size: one_to_two</li><li>Panel: liftgate, Condition: heavy_scratch, Size: one_to_two</li><li>Panel: right_quarter_panel, Condition: scratch_light, Size: one_to_two</li></ul> |             |              |            |              |
| Interior Damage: Yes                 | <ul style="list-style-type: none"><li>Panel: steering_wheel, Condition: scratch_light, Size: quarter_to_half</li></ul>                                                                                                                                                                                                                        |             |              |            |              |
| Mechanical Damage: No                |                                                                                                                                                                                                                                                                                                                                               |             |              |            |              |
| Notes                                |                                                                                                                                                                                                                                                                                                                                               |             |              | CR Score   |              |
|                                      |                                                                                                                                                                                                                                                                                                                                               |             |              | -          |              |