Condition Report

Prepared On: 08/21/2026 03:51 PM	**Dealership:** Drive a Dream
Masked VIN: XXXXXXXXXTU041783	**Year:** 2026
Make: Hyundai	**Model:** Palisade
Trim: XRT Pro	**Odometer:** 3643
Engine: 3.5L GDI + MPI V6 24v DOHC Engine	**Transmission:** Automatic
Body: SUV	**Fuel:** Gas
Exterior Color: Ecotronic Gray Pearl	**Interior Color:** Black

General Condition

Odometer Status:	**A/C Working:**
Prior Paint: No	**Engine Light On:** No
Total Panels Painted: 0	**ABS Light On:** No
Replaced Panels: No	**Airbag Light On:** No
Total Panels Replaced: 0	**Airbag Deployed:** No
Structural Damage: No	**History Check Problem:** No
Flood Damage: No	**Odor:** No
Fire Damage: No	**Glass Damage:** No
Hail Damage: No	**Mechanical Damage:** No
Number of Keys:	**Title Country:** United States
Number of Fobs:	**Title State:**
Keyless Entry: No	**Title Status:**
Manuals: No	**Title Type:**
Police Use: No	**Livery Use:** No
Taxi Use: No	**Grey Market:** No
Canadian Vehicle: No	**Sale Lights:** No Light

Wheels & Tires

Location	Condition	Tread Depth	Manufacturer	Wheel Size	Wheel Damage
Right Front					
Left Front					
Right Rear					
Left Rear					
Right Rear Inner					
Left Rear Inner					
Spare					

Damage

Prior Paint Location	
Prior Paint Condition	
Exterior Damage: No	
Interior Damage: No	
Mechanical Damage: No	

Notes	CR Score
	-